



P 80 EEX

C A T A L O G O P E Z Z I - S P A R E P A R T S L I S T : N R . 8 9 0 0 1 / C

>> E L E T T R O P O M P A P 8 0 E E X M O N O F A S E C o d . : P F - 3 1 9 <<

Pos.	DENOMINAZIONE	DESCRIPTION	MATERIALE	MATERIAL	Nr.Pz.
1	Base	Base	Fe	Iron	1
2	Motore Monofase	Single Phase Motor	-	-	1
3	Giunto d.14	Coupling d.14	Ghisa	Cast iron	1
4	Anello elastico	Rubber circlip	Plastica	Plastic	1
5	Rondella 6x18x2	Washer 6x18x2	R40	R40	2
6	Vite TE M6x16	Screw TE M6x16	Acciaio zincato	Galvanized steel	2
7	Rete di protezione	Wire net protection	Fe	Iron	1
8	Grano M6x10	M6x10 Grub-screw	Acciaio 12.9	Steel 12.9	2
9	Giunto d.20	Coupling d.20	Ghisa	Cast iron	1
10	Pompa P80	P80 Pump	-	-	1
11	Vite TE M8x25	Screw TE M8x25	Acciaio zincato	Galvanized steel	8
12	Rondella 9x24x2	Washer 9x24x2	R40	R40	1
13	Dadi M8x8	Nut M8x8	Acciaio zincato	Galvanized steel	8
14	Dadi M6x5	Nut M6x5	Acciaio zincato	Galvanized steel	2

>> V A R I A N T I E L E T T R O P O M P A P 8 0 E E X T R I F A S E C o d . : P F - 3 1 7 <<

2	Motore Trifase	Three Phase Motor	-	-	1
---	----------------	-------------------	---	---	---